

01306.000100



PATENT

Cgs

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: Thinh Nguyen
YUJI KAGAMI ET AL.)	
	:	Group Art Unit: 2861
Appl. No.: 10/601,524)	
	:	Confirmation No.: 7542
Filed: June 24, 2003)	
	:	
For: RECORDING APPARATUS)	
	:	
U.S. Patent No.: 6,991,331 B2)	
	:	
Issued: January 31, 2006)	June 22, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
JUN 27 2006
of Correction

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

06/23/2006 JADD01 00000007 6991331

01 FC:1811


100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

JUN 28 2006

Patentees' undersigned attorney may be reached in our Washington, D.C.
office by telephone at (202) 530-1010. All correspondence should continue to be directed to our
address given below.

Respectfully submitted,



Lawrence A. Stahl
Attorney for Patentees
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,991,331 B2
DATED : January 31, 2006
INVENTOR(S) : YUJI KAGAMI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 50, "easing 120" should read --casing 120--.
Line 57, "raise" should read --raises--.
Line 66, "a" should read --the--.

COLUMN 3:

Line 17, "to" should read --to the--.
Line 57, "tray," should read --tray.--.

COLUMN 7:

Line 40, "rote" should read --route--.

COLUMN 8:

Line 12, "131" should read --131.--.
Line 31, "switch" should read --switch.--.

COLUMN 10:

Line 5, "secure" should read --secured--.

COLUMN 11:

Line 35, "tray" should read --tray to--.

COLUMN 12:

Line 36, "tray 208." should read --tray 203.--.
Line 61, "delivers" should read --delivery--.

COLUMN 14:

Line 50, "ray" should read --tray--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,991,331 B2

No. of add'l. copies
@ 30¢ per page



JUN 28 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,991,331 B2

DATED : January 31, 2006

INVENTOR(S) : YUJI KAGAMI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15:

Line 43, "because" should read --because it--.

Line 67, "he" should read --the--.

COLUMN 16:

Line 37, "definition" should read --definition.--.

Line 50, "upon" should read --upon being--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,991,331 B2

No. of add'l. copies
@ 30¢ per page



JUN 28 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,991,331 B2

DATED : January 31, 2006

INVENTOR(S) : YUJI KAGAMI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 50, "easing 120" should read --casing 120--.

Line 57, "raise" should read --raises--.

Line 66, "a" should read --the--.

COLUMN 3:

Line 17, "to" should read --to the--.

Line 57, "tray," should read --tray.--.

COLUMN 7:

Line 40, "rote" should read --route--.

COLUMN 8:

Line 12, "131" should read --131.--.

Line 31, "switch" should read --switch.--.

COLUMN 10:

Line 5, "secure" should read --secured--.

COLUMN 11:

Line 35, "tray" should read --tray to--.

COLUMN 12:

Line 36, "tray 208." should read --tray 203.--.

Line 61, "delivers" should read --delivery--.

COLUMN 14:

Line 50, "ray" should read --tray--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,991,331 B2

No. of add'l. copies
@ 30¢ per page



JUN 28 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,991,331 B2

DATED : January 31, 2006

INVENTOR(S) : YUJI KAGAMI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15:

Line 43, "because" should read --because it--.

Line 67, "he" should read --the--.

COLUMN 16:

Line 37, "definition" should read --definition.--.

Line 50, "upon" should read --upon being--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,991,331 B2

No. of add'l. copies
@ 30¢ per page



JUN 28 2006